

0030



Norman H. Bangerter

Governor

Dee C. Hansen

Executive Director

Dianne R. Nielson, Ph.D.

Division Director

# State of Utah

DEPARTMENT OF NATURAL RESOURCES  
DIVISION OF OIL, GAS AND MINING

355 West North Temple

3 Triad Center, Suite 350

Salt Lake City, Utah 84180-1203

801-538-5340

August 23, 1988

Mr. Kim Mangum, Director  
Permitting & Compliance  
Co-Op Mining Company  
P. O. Box 1245  
Huntington, Utah 84528

Dear Mr. Mangum:

Re: PAP Amendment, NOV No. 88-26-12-2, #1 of 2, Lump Coal  
Storage, Co-Op Mining Company, Bear Canyon Mine,  
ACT/015/025-88(B), Folder #2, Emery County, Utah

The Division has completed review of your company's submittal received July 26, 1988. The plans were reviewed by Pamela Grubaugh-Littig of the Division's technical staff. Please resolve the following deficiencies as outlined in the attached memo by September 9, 1988.

In the interim, Co-op is approved to store lump coal at its present location until October 31, 1988

If you have any questions on this matter, please call Pamela Grubaugh-Littig or me.

Sincerely,

John Whitehead  
Permit Supervisor/  
Reclamation Hydrologist

djh

Attachment(s)

cc: E. Kingston

G. Hansen

J. Helfrich

WP+7/6



# State of Utah

DEPARTMENT OF NATURAL RESOURCES  
DIVISION OF OIL, GAS AND MINING

Norman H. Bangerter

Governor

Dee C. Hansen

Executive Director

Dianne R. Nielson, Ph.D.

Division Director

355 West North Temple

3 Triad Center, Suite 350

Salt Lake City, Utah 84180-1203

801-538-5340

August 3, 1988

TO: John Whitehead, Permit Supervisor

FROM: Pamela Grubaugh-Littig, Reclamation Engineer *pag*

RE: Lump Coal Storage Area (Received July 26, 1988), Bear Canyon Mine, Co-Op Mining Company, ACT/015/025-88B, Folder No. 2, Emery County, Utah

## Synopsis of Proposal

Co-Op Mining Company (Co-Op) is temporarily storing lump coal on the Scale House pad, occupying about a one-half acre area. The letter from Co-Op Mining dated July 19, 1988 outlined the two justifications for this temporary coal storage pad: convenience and safety for Co-Op customers.

## Analysis

Co-Op must identify a permanent location for the temporary coal storage area on the surface facilities map (Plate 2-2) required by UMC 784.23[b][4]. The narrative in the PAP must incorporate a description of the use, maintenance and removal of this coal storage area (UMC 784.11[b][3]).

## Recommendations

The applicant must provide the above-mentioned information for insertion into the PAP before the Division can approve this proposal.

djh  
9075R/55